



NO	Parts Number	Parts name	Quantity
1	AZ1642160064	Instrument panel beam welding assembly	1
	Q1460825	Combination bolt	8

Note: 1. The harness and the beam assembly are pre-assembled and connected by fastening straps;

2. The welding nut of the welding bracket on the hood should be located in the middle of the long hole of the bracket during assembly. This position determines the distance between the middle of the instrument panel and the hood gasket.